

NEPAL PREMIUM

Rękawice ochronne

Rękawice wykonane są z najwyższej jakości bydlęcej skóry licowej oraz wytrzymałej tkaniny.

Wyposażone są w usztywniany mankiet.

Wzmocnienia śródreżca oraz wzmocnienia końców palców posiadają podwójne szwy zwiększające trwałość.

Podszywka w części chwytnej zapewnia komfort w trakcie użytkowania.

Rękawice charakteryzują się dobrą odpornością na ścieranie i rozdieranie oraz korzystną relacją ceny do jakości.

Spełniają wymagania zasadnicze dla środków ochrony indywidualnej zawarte w Rozporządzeniu (UE) 2016/425 oraz w normach zharmonizowanych: EN 21420 i EN 388.



Informacje techniczne:

Materiał	bydlęca skóra licowa, tkanina
Poziom skuteczności	3133X
Rozmiary	8, 9, 10, 11
Kod zamówienia	R-I-NEPALPREMIUM

EN 388 Rękawice chroniące przed zagrożeniami mechanicznymi

		1	2	3	4	5	
 EN 388 3133X*	*Poziom skuteczności						
	Odporność na ścieranie / liczba cykli	100	500	2000	8000	-	
	Odporność na przecięcie / wskaźnik	1,2	2,5	5	10	20	
	Odporność na rozdieranie [N]	10	25	50	75	-	
Odporność na przekłucie [N]		20	60	100	150	-	
		A	B	C	D	E	F
Odporność na przecięcie (TDM) [N]		2	5	10	15	22	30

znak X – badanie nie zostało wykonane



NEPAL PREMIUM

Protective gloves

Made of the highest quality cow grain leather and resistant woven fabric.

They are provided with rubberized cuff.

Metacarpus and finger tips are strengthened with double seams which increase life period of the gloves.

Lining fabric in the palm guarantees comfort of usage.


The gloves meet general requirements for personal protective equipment provided in Regulation (EU) 2016/425 and in the Harmonized Standards: EN 21420 and EN 388.



Technical Information:

Material:	cow grain leather, fabric, rubberized cuff
Performance level:	3133X
Sizes:	8, 9, 10, 11
Order numbers:	R-I-NEPALPREMIUM

EN 388 Protective gloves against mechanical risks

		1	2	3	4	5	
 EN 388 3133X*	*Performance level						
	Resistance to abrasion / cycles	100	500	2000	8000	-	
	Cut resistance / index	1,2	2,5	5	10	20	
	Tear strength [N]	10	25	50	75	-	
	Puncture resistance [N]	20	60	100	150	-	
		A	B	C	D	E	F
Cut resistance (TDM) [N]		2	5	10	15	22	30

The letter X means that the test was not preformed.

