

LAMFLEX

Rękawice ochronne

Rękawice w całości wykonane z najwyższej jakości licowej skóry owczej.

Rękawice przeznaczone są do prac wymagających dobrej manipulacyjności.

Miękka skóra zapewnia wyjątkowy komfort użytkowania. Guma ściągająca na wysokości nadgarstka sprawia, że rękawice dopasowują się do dłoni.

Zróżnicowana kolorystyka lamówki służy do identyfikacji rozmiarów.

Spełniają wymagania zasadnicze dla środków ochrony indywidualnej zawarte w Rozporządzeniu (UE) 2016/425 oraz normach zharmonizowanych: EN ISO 21420 i EN 388.



Identyfikacja rozmiarów za pomocą kolorów obszycia mankietów:

8  9  10 

Informacje techniczne:

Materiał owcza skóra licowa

Poziom skuteczności 1121X

Rozmiary 8, 9, 10

Kod zamówienia I-LAMFLEX-XX*

*proszę wstawić rozmiar w miejscu XX

EN 388 Rękawice chroniące przed zagrożeniami mechanicznymi

EN 388	*Poziom skuteczności	1	2	3	4	5	
 1121X*	Odporność na ścieranie / liczba cykli	100	500	2000	8000	-	
	Odporność na przecięcie / wskaźnik	1,2	2,5	5	10	20	
	Odporność na rozdzieranie [N]	10	25	50	75	-	
	Odporność na przekłucie [N]	20	60	100	150	-	
		A	B	C	D	E	F
Odporność na przecięcie (TDM) [N]		2	5	10	15	22	30

znak X – badanie nie zostało wykonane



LAMFLEX

Protective Gloves

Gloves entirely made of the highest quality sheep grain leather.

Gloves designed for works which require good dexterity.

Soft skin to ensure high comfort of use.

Wrist welt makes the gloves fit the hand.

To make it easier to identify the sizes, the gloves are provided with coloured cuff ribbing.

The gloves meet general requirements for personal protective equipment provided in Regulation (EU) 2016/425 and in the Harmonized Standards: EN ISO 21420 and EN 388.



Size identification by variously coloured cuff ribbing:



Technical Information:

Material: sheep grain leather

Performance level: 1121X

Sizes: 8, 9, 10

Order numbers: I-LAMFLEX-XX*

*insert size for XX

EN 388 Protective gloves against mechanical risks

EN 388	*Performance level	1	2	3	4	5	
 1121X*	Resistance to abrasion / cycles	100	500	2000	8000	-	
	Cut resistance / index	1,2	2,5	5	10	20	
	Tear strength [N]	10	25	50	75	-	
	Puncture resistance [N]	20	60	100	150	-	
	Cut resistance (TDM) [N]	A	B	C	D	E	F
		2	5	10	15	22	30

The letter X means that the test was not preformed.

